

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

EC639 APT BUILDING/BRIGHTON HOUSE
ESE 500 BRIGHTWATER COURT
1/2-1 BROOKLYN, NY

NY Spills S120700241
N/A

0.947 mi.
5001 ft.

Site 1 of 3 in cluster EC

Relative:
Higher

SPILLS:

Actual:
8 ft.

Name: APT BUILDING/BRIGHTON HOUSE
Address: 500 BRIGHTWATER COURT
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1311080 / 2017-02-28
Facility ID: 1311080
Facility Type: ER
DER Facility ID: 446925
Site ID: 491963
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: D4
SWIS: 2401
Spill Date: 2014-02-24
Investigator: RMPiPER
Referred To: Not reported
Reported to Dept: 2014-02-24
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2014-02-24
Spill Record Last Update: 2017-02-28
Spiller Name: EGOR
Spiller Company: APT BUILDING/BRIGHTON HOUSE
Spiller Address: 500 BRIGHT WATER COURT
Spiller Company: 999
Contact Name: EGOR
DEC Memo: "Leaking fill. Found out there was no spill number already. Line has been dug up and a temp clamp was put on it. Permanent repair to be made and report will be sent to my attention. 9/9/15- left message for Greg Q requesting info for closure. 5/5/16- left message for Greg Q requesting info for closure. 2-239968 5/6/16- DEC Piper received and reviewed closure report dated 6/18/14. Based on work to date, , and removal of 35 tons of contaminated soil, this spill can be closed however tank is overdue for tightness test. Greg Q does not have contact info as the managing agent has changed hands. 2/28/17- DEC Piper- Tank has been tested though failed. Repairs and retest underway. See spill 1610329. 1311080 spill closed. "
Remarks: "possible loss Of 500 to 1000 gals/investigation underway"

All Materials:

Site ID: 491963
Operable Unit ID: 1241504
Operable Unit: 01
Material ID: 2241926
Material Code: 0001A
Material Name: #2 fuel oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported